

<b>Recall Ref</b>	<b>Make</b>	<b>Model</b>	<b>Concern</b>	<b>Numbers</b>
NCA/2009/001	VW	Passat	Moisture may enter the servo due to poor maintenance - no affect on braking performance	29,000
NCA/2009/002	Hyundai	Elantra	SRS Warning light may illuminate - rear passenger may disturb wiring	3422
NCA/2009/003	Suzuki Motorcycles	GSXR1000	Frame cracking may occur due to abuse - no design or construction deficiency	3938