

1st August 2006 to 31st July 2007
Volumes of Annual Tests, Fail Rates, % Fail Rates and

Note: a vehicle may have more than one defect allocated to it

Date	Total Tests	Total Fails	Final Fail Rate	Seat belts *	Exhaust emissions *	Road wheels and hubs	Size and type of tyres
				Test Item 3	Test Item 5	Test Item 6	Test Item 7
Aug-06	39,439	8,679	22.01%	444	239	303	196
Sep-06	40,207	8,577	21.33%	446	117	293	144
Oct-06	41,169	9,064	22.02%	469	67	334	184
Nov-06	39,010	8,920	22.87%	438	78	316	166
Dec-06	26,318	5,908	22.45%	335	54	184	102
Jan-07	36,541	7,763	21.24%	358	82	254	135
Feb-07	36,852	7,678	20.83%	312	63	258	138
Mar-07	44,062	9,518	21.60%	377	75	296	204
Apr-07	38,940	7,698	19.77%	302	66	242	144
May-07	42,427	8,953	21.10%	310	78	301	145
Jun-07	42,780	9,150	21.39%	340	96	274	196
Jul-07	41,998	9,252	22.03%	345	81	339	167
Sum:	469,743	101,160	21.5%	4,476	1,096	3,394	1,921

As at 26/03/09	Ref. CIS914	Created by CIS
(Please quote the above Ref in all correspondence)		



Defects for Motor Vehicles

Condition of tyres	Sideguards, rear under-run devices and bumper bars	Spare wheel/carrier	Vehicle to trailer coupling	Trailer parking, emergency brakes and air line connections	Spray suppression. wings and wheel arches	Cab security *
Test Item 8	Test Item 9	Test Item 10	Test Item 11	Test Item 12	Test Item 14	Test Item 15
586	290	0	93	1	416	68
585	301	1	95	9	454	53
630	330	5	130	5	437	49
623	368	3	85	7	447	65
410	227	2	78	4	331	39
548	293	2	104	9	438	38
530	289	2	108	8	416	40
721	465	3	124	13	506	60
565	424	1	91	7	378	45
591	512	1	110	9	411	68
612	464	0	108	7	412	54
630	352	5	126	6	431	76
7,031	4,315	25	1,252	85	5,077	655

Cab doors	Cab floor and steps *	Driver's seat *	Security of body	Exterior of body	Mirrors *	Glass and view of the road *
Test Item 16	Test Item 17	Test Item 18	Test Item 19	Test Item 20	Test Item 22	Test Item 23
7	33	17	57	73	50	334
5	22	10	63	58	39	361
4	23	15	76	81	61	326
0	24	17	63	69	56	347
5	19	12	49	55	44	235
11	17	15	68	52	64	255
6	8	4	45	74	44	281
7	27	13	64	82	57	380
6	23	6	49	43	51	286
8	22	10	50	62	55	353
5	22	14	68	79	53	350
7	32	8	57	92	57	406
71	272	141	709	820	631	3,914

Windscreen wipers and washers *	Speedometer/tachograph *	Horn *	Driving controls *	Steering control *	Speed limiter *	Pressure /vacuum warming and build-up *
Test Item 25	Test Item 26	Test Item 27	Test Item 28	Test Item 30	Test Item 33	Test Item 34
255	739	127	96	20	277	45
296	717	121	88	15	307	30
263	839	122	101	17	333	46
281	834	148	95	16	312	44
236	543	94	65	8	227	27
266	719	121	90	14	905	44
337	728	128	86	8	851	35
302	869	163	104	14	950	30
269	762	125	84	12	826	38
295	919	133	96	15	814	47
316	933	127	101	17	870	58
332	972	128	90	11	887	40
3,448	9,574	1,537	1,096	167	7,559	484

Hand lever operating mechanical brakes *	Service brake pedal	Service brake operation	Hand operated brake control valves	Condition of chassis	Electrical wiring and equipment	Engine and transmission mountings *
Test Item 36	Test Item 37	Test Item 38	Test Item 39	Test Item 41	Test Item 42	Test Item 43
4	10	141	22	30	432	28
10	10	156	11	21	402	14
9	8	181	29	28	457	21
7	17	155	21	20	494	25
5	8	117	23	15	328	20
8	12	149	21	12	398	14
7	8	143	19	21	329	16
15	9	202	19	21	434	21
8	15	139	15	25	407	23
7	20	178	17	19	473	25
9	15	190	17	24	454	29
11	21	144	22	18	528	21
100	153	1,895	236	254	5,136	257

Oil leaks	Fuel tanks and systems	Exhaust systems *	Suspension	Axles, stub axles and wheel bearings	Steering mechanism	Transmission
Test Item 44	Test Item 45	Test Item 46	Test Item 48	Test Item 53	Test Item 54	Test Item 57
164	396	222	873	185	880	236
160	366	204	799	205	862	220
150	376	213	961	191	975	250
170	465	232	999	211	958	242
99	261	155	628	140	675	154
117	331	184	835	172	749	201
118	354	164	787	150	784	206
160	414	214	967	187	1003	257
137	388	190	696	145	745	196
161	366	256	909	181	869	234
172	406	221	925	198	921	262
175	414	268	911	202	905	257
1,783	4,537	2,523	10,290	2,167	10,326	2,715

Brake systems and components	Reflectors and rear markings	Lamps	Direction indicators and hazard warning lamps	Aim of headlamps	Service brake performance	Secondary brake performance
Test Item 59	Test Item 62	Test Item 63	Test Item 66	Test Item 67	Test Item 71	Test Item 72
1934	688	3086	845	9470	3072	1971
1978	676	2919	878	9650	2878	1881
2175	705	3180	937	10514	2934	1938
2209	696	3150	902	10062	2757	1794
1426	495	2150	578	6484	1833	1171
1726	610	2685	722	8602	2203	1416
1736	627	2700	750	8562	2256	1448
2226	700	3258	854	9834	2857	1767
1752	556	2717	714	8371	2419	1570
2108	629	3086	850	9479	2729	1804
2083	650	3088	877	9758	2864	1856
2213	654	3209	887	9418	2970	1888
23,566	7,686	35,228	9,794	110,204	31,772	20,504

Parking brake performance	Other dangerous defects
Test Item 73	Test Item 74
1244	3
1178	8
1210	3
1074	3
795	1
884	4
868	2
1127	1
879	7
1082	1
1099	2
1208	4
12,648	39