

Roadworthiness Prohibition Notice

Operator / Driver Details	
Operator Licence No.	

Vehicle Details	
Prohibited Vehicle ID	
Make	
Towing Vehicle Reg.	
Odometer Reading	

Defects

The defects leading to the prohibition are shown below and on continuation pages where necessary.

Severity	Defect Description	Code
IM No. 59 I	Load sensing valve seized, clearly not able to function as intended, linkage not connected.	36S
IM No. 41 D	Chassis cross member fractured, but does not immediately affect control of the vehicle, o/s & n/s, forward of rear axle, below suspension A frame mounting.	20S
IM No. 59 D	Brake valve insecure, due to a failure of supporting structure, axle 4.	24S
IM No. 48 D	Suspension component defective, control of vehicle likely to be affected, axle 4, main axle locating bushes worn, allowing o/s & n/s rear wheels to make contact with suspension beams.	20S
		100

This prohibition indicates a significant failure in maintenance

I hereby prohibit all driving and towing of this vehicle on public roads. This prohibition comes into force on ___ / ___ / ___ at ___ : ___ and it will stay in force until it is removed by prior appointment at an Official Testing Station by full inspection.

Issuing Officer Details		Receipt Details	
Signature		Signature	
Name		Name	
Date of Issue			
Time of Issue			
Place where issued			

Variation Details

Signature		Date of issue	
Name		Time of issue	